



PS MANUAL

MULTIMETER ACCESSORIES

1.0 Model **MM-PA20**

2.0 Description

Pressure Adaptor



Durst Industries Australia Pty. Ltd.

durst.com.au

Phone: +61 2 9660 1755

Unit 1, 11 Packard Avenue
Castle Hill NSW 2154 Australia





PS MANUAL

3.0 Features

- Plugs into your Multimeter

4.0 Physical and Dimensional Properties

- Each unit weighs approximately 151 g
- Width 56 mm
- Length 100 mm
- Height 35 mm

5.0 Performance

- Pressure Range 1 – 500 psi (Accuracy $\pm 1\%$ of reading ± 0.3 psi)
- Vacuum Range 30 inHg (Accuracy $\pm 1\%$ of reading ± 0.5 inHg)
- Pressure Port connection $\frac{1}{2}$ inch NPT
- Cable length 2m
- Power consumption 7.3mA

6.0 Uses

- Ideal for Durst or Fluke Multimeters

7.0 Documentation

- Bar Code Number: **9346080001898**
- Product Specification Manual - PS 202
- Work Instruction Manual - WI 202
- Product Costing Manual - PC 202

Durst Industries Australia Pty. Ltd.

durst.com.au

Phone: +61 2 9660 1755

Unit 1, 11 Packard Avenue
Castle Hill NSW 2154 Australia

